
TRANSISTOR MOUNTING PADS



KeyD = Glass Filled Polyester
N / WN = Nylon / White Nylon
GFN = Glass Filled Nylon
P = PolypropyleneSuggested Continuous Operating Temp range = -40° C to $+160^{\circ}$ C
Suggested Continuous Operating Temp range = -40° C to $+80^{\circ}$ C
Suggested Continuous Operating Temp range = -40° C to $+110^{\circ}$ C
Suggested Continuous Operating Temp range = -20° C to $+80^{\circ}$ C