




RS- 8607191

Air Heater , 1/2"OD,5" Length, 400W



f

Air heaters feature an open coil of high temperature resistance wire electrically isolated in a stainless steel sheath. Because the air being heated passes directly over the resistance wire, maximum heat transfer efficiency is achieved. Air heaters are used for heat staking, plastic welding, laminating, drying, heat sealing, and any other operation where air needs to be heated up to 500°C

Technical Specifications:

- OD : 1/2"
- Length : 5"
- Voltage : 120V AC
- Wattage : 400W
- Lead wires : 10 inch long
- Lead wire insulation : Fiberglass