



**Electrical Testers > Electrical Testers >** 

## Fluke 9040 Phase Rotation Indicator



## Phase rotation indicator with high voltage capability for industrial applications

The Fluke 9040 is effective for measuring phase rotation in all areas where three phase supplies are used to feed motors, drives and electrical systems. The Fluke 9040 is a rotary field indicator and can provide clear indication of the 3 phase via an LCD display and the phase rotation direction to determine correct connections. It allows rapid determination of phase sequence and has a voltage (up to 700 V) and frequency range suitable for commercial and industrial applications. The included test probes have a variable clamping range for safe contact, also in industrial sockets.



<b>Model Name</b>	Description	
Fluke 9040	Phase Rotation Indicator  3 self-retaining test probes (black) alligator clip user manual	