



Accessories > Cables & Hardware >

OC4USB USB interface cable



- Connects the optical isolated serial to USB adapter
- Supports the Fluke 120 Series, 190 Series ScopeMeter and the 430 Series Power Quality analyzer
- Supports Windows Vista/ XP/2000/Me/98 Second edition

Model Name	Description
OC4USB	USB interface cable