
M16 powerfast Connectivity


M16 Powerfast Cordset Part Number Key




Part Number Keys are to assist in IDENTIFICATION ONLY. Consult factory for catalog items not identified.




Extension Examples






Note: Only one male connector per tee available.


Extension Examples






M16 Powerfast Receptacle Part Number Key

Part Number Keys are to assist in IDENTIFICATION ONLY. Consult factory for catalog items not identified.









S


2 В K

BSM/BKM = male trunk(2) and female drop(3) BKM/T female trunk(2) and cable drop(3) BSM/BKM = male trunk(2) and female drop(3) = female trunk(2) and cable drop(3)

Note: Only one male connector per tee available.







44