


SPARE CONTACTS F. SIZE S10 F. CONTACTOR  
 3RT1064,110KW/AC-3 CONSISTS OF 3 MOVABLE AND 6  
 FIXED CONTACTS WITH FIXING PARTS



Certificates/approvals:

Declaration of  
 Conformity

Test Certificates



EG-Konf.

[Special Test Certificate](#)

Shipping Approval



GL



LRS



PRS



RINA

Shipping Approval

other



RMRS

[Confirmation](#)

[other](#)

[Environmental Confirmations](#)

Further information:

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.com/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<http://www.siemens.com/industrial-controls/mall>

CAx-Online-Generator

<http://www.siemens.com/cax>

---

**Service&Support (Manuals, Certificates, Characteristics, FAQs,...)**

<http://support.automation.siemens.com/WW/view/en/3RT1964-6A/all>

---

**Image database (product images, 2D dimension drawings, 3D models, device circuit diagrams, ...)**

[http://www.automation.siemens.com/bilddb/cax\\_en.aspx?mlfb=3RT1964-6A](http://www.automation.siemens.com/bilddb/cax_en.aspx?mlfb=3RT1964-6A)

---

**last change:**