

Professionally approved products.

Product Datasheet Foot Switch Switch Pushbutton Alternate-Acting





Package Contain:

- 1 x Foot Switch
- 2 x Hex Nut
- 1 x Washer
- 1 x Ring

Specification:

SWITCH TYPE:		8466720
POLES/THROWS:		SPDT
SWITCH FUNCTIONS:		ON-ON
ELECTRICAL & MECHANICAL CHARACTERISTICS	CONTACT RATING:	2A @ 250VAC, 4A @ 125VAC, 2A @ 24VDC, 4A @ 12VDC
	ELECTRICAL LIFE:	20,000 make-and-break cycles at full load
	MECHANICAL LIFE:	Min. 20,000 cycles without load
	CONTACT RESISTANCE:	50m-ohms max. initial @ 2-4VDC, 100mA
	INSULATION RESISTANCE:	Apply 500VDC for 1min±5sec. After which measurement to be made between live parts and dead-metal parts shall result 100M-ohms min.
	DIELECTRICAL STRENGTH:	1,500VAC (50Hz-60Hz) RMS @ sea level shall result no damage to parts arcing or flashover
	OPERATING TEMPERATURE:	-20Celsius degree to +65Celsius degree
	SOLDERING ABILITY:	Per MIL-STD-202F method 208D,max soldering temperature @ 260Celsius degree, flux 5-10sec, duration of solder immersion 5+/-1sec. shall result no anti-soldering and the coverage of dipping into solder must be more than 90%
	TORQUE:	Max. 3kgf applied to nut
	OPERATING FORCE:	1500+/-200gf
	SOLDERING ABILITY:	Per MIL-STD-202F method 208D,max soldering temperature @ 260Celsius degree, flux 5-10sec, duration of solder immersion 5+/-1sec. shall result no anti-soldering and the coverage of dipping into solder must be more than 90%
	COLD TEST:	Stored at temperature –20(+/-2)Celsius degree for 48 hours, shall result no changes to switch's electrical performance
	HOT TEST:	Stored at temperature +65(+/-2)Celsius degree for 48 hours, shall result no changes to switch's electrical performance
	HUMIDITY TEST:	Stored at temperature 40(+/-2)Celsius degree with relative humidity 90%~95% for 48 hours, shall result no changes to switch's electrical performance
	SALT SPRAY RESISTANCE:	Stored at temperature @ 35(+/-3)Celsius degree, and salt solution concentration of 5% with full air temperature @ 47(+/-3) Celsius degree and air pressure 1.0kg for 48 hours. The switch shall result no corrosion as well as no apparent changes to its functional performance. Per ASTM-B117 & JIS-Z371 STD.
CH ARA CTE	BASE:	PA66, flame retardant, heat stabilized (UL 94V-0)





PLUNGER:	Brass, nickel plated
BUSHING:	Brass, nickel plated
CAP:	Brass, nickel plated
COVER:	Stainless steel
PIVOT PIN:	Brass or POM
SPRING:	Piano wire
MOVABLE CONTACT:	Copper alloy, tin plated
TERMINAL CONTACT:	Copper alloy, tin plated
ALL TERMINALS:	Copper alloy, tin plated
	Nut – brass, nickel plated
HARDWARE:	Washer – steel, nickel plated
	Ring – POM
HAND SOLDERING:	Max soldering temperature @ 360Celsius degree, immersion time 4sec.
WAVE SOLDERING:	No-clean flux wave soldering is recommended so the switch does not require washing after soldering process. Noted, not to have flux migrate inside the switch through the top of the housing or actuator to prevent contamination. Max temperature @ 260Celsius degree (500F) for 3 sec.
CLEANING PROCESS:	Noted, the switch is "not totally sealed" so it is important not to immerse/spray or clean unsealed areas of the switch during flux removal. Improper cleaning could cause switch deficiencies such as intermittence or open contact failures
INTERNAL PACKAGING:	1pcs per PE bag
RoHS IDENTIFICATIONS:	Bag is attached with a label marking "RoHS"
The switch is suitable for (Contact rating section)	power rated applications, rating recommendation is per aforementioned above
Problem relates to terminal oxidization can be prevented by storing product in an environment that is dry and cool with the relative humidity less than 90%. Noted, prior to mounting products onto circuit board as well as for unused units, it is recommended to keep them in the bag and with the bag sealed.	
	BUSHING: CAP: COVER: PIVOT PIN: SPRING: MOVABLE CONTACT: TERMINAL CONTACT: ALL TERMINALS: HARDWARE: HAND SOLDERING: WAVE SOLDERING: CLEANING PROCESS: INTERNAL PACKAGING: ROHS IDENTIFICATIONS: The switch is suitable for (Contact rating section) Problem relates to termin cool with the relative hum







