CABLE ASSEMBLY INSTRUCTION

Maple Model(s) HMI504T HMI5043N/T

PLC or Controller

Allen-Bradley MicroLogix[™] 1000, 1100, 1200 and 1500

Communication Type


RS-232 with 8-pin Connector at PLC



Summary

The 8-pin connector for the Allen-Bradley MicroLogix[™] 1000, 1100, 1200 or 1500 PLC is a special part only available through Allen-Bradley. We recommend that you purchase Maple Systems' Cable (P/N 7444-0040) or purchase a cable from Allen-Bradley. This wiring diagram shows how Maple Systems' Cable (P/N 7444-0040) is assembled.

Drawing and Schematic



Notes

1> Shield wire must be terminated to connector metal shell.

Maple Systems Inc., 808 134th Street SW, Suite 120, Everett, WA 98204-7333 www.maplesystems.com