




Test Plugs 4 mm System



Drawing

Measurements are shown in millimeters. Multiply by 0.03937 to convert to inches.





* Please consider derating graph on page 80.